




## Replaces Scag STTII - Turf Tiger II Parts

52in Zero-Turn Mower

52in Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Scag STTII - Turf Tiger II Parts

52in Zero-Turn Mower  
52in Deck



| Item No                      | R&R Part No.        | OEM Part No.      | Description                                      | Qty Req | Order Quantity |
|------------------------------|---------------------|-------------------|--------------------------------------------------|---------|----------------|
| <b>Overhaul, Kit</b>         |                     |                   |                                                  |         |                |
| 44                           | <b>RZS481022</b>    | 481022            | Bearing Assembly                                 | 3       |                |
| 1                            | <b>RRB3155-1800</b> | 422372,<br>482878 | Mower Blade - High-Lift 18 x 2.5in x 5/8 Mt Hole | 3       |                |
| <b>Wheels</b>                |                     |                   |                                                  |         |                |
| 10                           | <b>RZS481632</b>    | 481632            | Wheel - Anti Scalp                               | 2       |                |
| 11                           | <b>RZS48038</b>     | 48038             | Guide Roller                                     | 1       |                |
| <b>Belts</b>                 |                     |                   |                                                  |         |                |
| 20                           | <b>RZS482281</b>    | 482281            | Belt - Deck                                      | 1       |                |
| <b>Other Parts Available</b> |                     |                   |                                                  |         |                |
| 40                           | <b>RZS461663</b>    | 461663            | Spindle Assembly                                 | 3       |                |
| 41                           | <b>RZS43644</b>     | 43644             | Spindle Housing                                  | 3       |                |
| 42                           | <b>RZS43589</b>     | 43589             | Spindle Shaft                                    | 3       |                |
| 43                           | <b>R366649</b>      | 481024            | Seal                                             | 3       |                |
| 45                           | <b>RZS43312</b>     | 43312             | Spacer - Outside                                 | 3       |                |
| 47                           | <b>RZS43296</b>     | 43296             | Spacer - Inside                                  | 3       |                |
| 49                           | <b>RZS481025</b>    | 481025            | Seal - Bottom                                    | 3       |                |
| 50                           | <b>RZS43297</b>     | 43296,<br>43297   | Spindle Bushing                                  | 3       |                |
| 51                           | <b>RZS481035</b>    | 481035            | Nut - Special 1-1/16 - 18                        | 3       |                |
| 52                           | <b>RZS43590</b>     | 43590             | Spacer - Spindle Bottom                          | 3       |                |
| 54                           | <b>RZS461842</b>    | 461842            | Idler Arm Weldment - with Bearing                | 1       |                |
| 55                           | <b>RZS48224</b>     | 48224             | Bearing                                          | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Scag STTII - Turf Tiger II Parts

52in Zero-Turn Mower

52in Deck



| Item No | R&R Part No.     | OEM Part No. | Description               | Qty Req | Order Quantity |
|---------|------------------|--------------|---------------------------|---------|----------------|
| 57      | <b>RZS43681</b>  | 43681        | Pivot - Idler             | 1       |                |
| 59      | <b>RZS461516</b> | 461516       | Push Arm Assembly LH & RH | 2       |                |
| 61      | <b>RZS451240</b> | 451240       | Rod Weldment - Pusharm    | 1       |                |
| 64      | <b>RZS422478</b> | 422478       | Bracket - Anti Scalp      | 2       |                |
| 65      | <b>RZS424677</b> | 424677       | Baffle - Turbo            | 1       |                |
| 66      | <b>RZS483215</b> | 483215       | Pulley - Idler 5 in       | 1       |                |
| 67      | <b>RZS483704</b> | 483704       | Spring                    | 1       |                |
| 68      | <b>R170714</b>   | 48677        | Fitting - Pressure Relief | 3       |                |
| 69      | <b>R302-5</b>    | 48114-04     | Fitting - Grease          | 3       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.