


Replaces Toro Z500 Z Master Parts



72in TURBO FORCE Side Discharge Mower
Caster Wheel





Replaces Toro Z500 Z Master Parts



Qty

72in TURBO FORCE Side Discharge Mower Caster Wheel

	Part No.	Part No.	Description	Req Quantity
Whee	els			
10	RCT5121861	1-523009, 126-5959	Tire - 13x6.50-6 Nhs (4 Ply) Carlisle Smooth	2
Othe	r Parts Availal	ble		
70	R116-8888	103-1474-01, 116-6707-01, 116-8888	Fork - Caster 7.875 in Inside	2
71	R103-4882	103-4882	Grease Cap - Castor	2
72	R3296-51	3296-51, 3296-81	Nut - Nylon Lock 3/4-10 Gr 8	2
73	R1-633508	1-633508	Washer - Spring Disc	6
74	R254-94	1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330	Tapered Bearing Cone	4
75	R254-72	01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511	Cup - Bearing	4
76	R1-543511	1-543511	Seal- Grease	2
77	R103-2768	103-2768	Guard - Seal	4
78	R103-3051	103-3051	Spacer - Nut - Hardened	4
79	R103-0063	103-0063	Seal - Grease	4
80	R500534	1-633585	Bearing - with Cup	4

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z500 Z Master Parts



Qty

72in TURBO FORCE Side Discharge Mower Caster Wheel

No	Part No.	Part No.	Description	Req	Quantity
	Detail Descrip	otion: Kit includes	: 1 ea R254-78- Bearing Cone & R254-79 Bearing Cone:		
81	R103-5156	103-5156	Axle- Caster	2	
82	R254-79	01-103-0060, 01-103-0130, 1-633584, 252-106, 254-79, 32-7800, 32-9590	Cup - Bearing	4	
	Detail Descrip	otion: Use R254-7	9M installation mandrel to properly install race.:		
83	RF5003	32127-29, 32131-5, 32132-5, 3296-23	Locknut - ESNA 1/2-13	2	
84	R325-39	325-39	Bolt - Hx HD 1/2-13 x 9 1/2	2	