

Coupling - Compression w/Floloc 1 RG11210





Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer Flo Control Manufacturer's 112-10 Model No

O.J. Company 294 Rang St-Paul Sherrington, JOL 2NO 450-247-2758