




## Replaces Toro Greensmaster 300 Parts

*Dethatcher Unit - Model 04479*

*Rear Roller Brush - Model 04650*



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro Greensmaster 300 Parts

*Dethatcher Unit - Model 04479*

*Rear Roller Brush - Model 04650*



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

### Belts

|   |                  |          |               |   |  |
|---|------------------|----------|---------------|---|--|
| 1 | <b>R105-5720</b> | 105-5720 | Belt - Poly V | 1 |  |
|---|------------------|----------|---------------|---|--|

### Rollers

|    |                  |                       |                     |   |  |
|----|------------------|-----------------------|---------------------|---|--|
| 10 | <b>R105-6792</b> | 104-1829,<br>105-6792 | Brush - Rear Roller | 1 |  |
|----|------------------|-----------------------|---------------------|---|--|

### Other Parts Available

|    |                 |                     |                |   |  |
|----|-----------------|---------------------|----------------|---|--|
| 21 | <b>R251-259</b> | 251-259,<br>251-307 | Bearing - Ball | 1 |  |
|----|-----------------|---------------------|----------------|---|--|

|    |                  |          |               |   |  |
|----|------------------|----------|---------------|---|--|
| 22 | <b>R115-7143</b> | 115-7143 | Spring - Wave | 1 |  |
|----|------------------|----------|---------------|---|--|

|    |                  |          |          |   |  |
|----|------------------|----------|----------|---|--|
| 23 | <b>R104-1830</b> | 104-1830 | Bolt - J | 2 |  |
|----|------------------|----------|----------|---|--|

|    |                |                                 |                |   |  |
|----|----------------|---------------------------------|----------------|---|--|
| 24 | <b>R3296-2</b> | 32127-10,<br>3296-2,<br>9157404 | Nut - #10 Lock | 2 |  |
|----|----------------|---------------------------------|----------------|---|--|

|    |                  |          |                   |   |  |
|----|------------------|----------|-------------------|---|--|
| 25 | <b>R112-6957</b> | 112-6957 | Washer - Hardened | 2 |  |
|----|------------------|----------|-------------------|---|--|

|    |                  |          |                  |   |  |
|----|------------------|----------|------------------|---|--|
| 26 | <b>R104-4727</b> | 104-4727 | Ring - Retaining | 1 |  |
|----|------------------|----------|------------------|---|--|

|    |                  |          |                                      |   |  |
|----|------------------|----------|--------------------------------------|---|--|
| 27 | <b>R121-4600</b> | 121-4600 | Locknut - 3/8-16 Hx HD Jam Nylon Ins | 1 |  |
|----|------------------|----------|--------------------------------------|---|--|

|    |                  |          |                           |   |  |
|----|------------------|----------|---------------------------|---|--|
| 28 | <b>R32128-33</b> | 32128-33 | Nut - 1/4-20 Flanged Serr | 2 |  |
|----|------------------|----------|---------------------------|---|--|

|    |                |                                                                                                            |                       |   |  |
|----|----------------|------------------------------------------------------------------------------------------------------------|-----------------------|---|--|
| 28 | <b>R301504</b> | 2296-42,<br>301504,<br>32127-24,<br>32128-33,<br>32146-17,<br>3296-16,<br>3296-42,<br>3296-42 ,<br>915661P | Locknut - ESNA 1/4-20 | 2 |  |
|----|----------------|------------------------------------------------------------------------------------------------------------|-----------------------|---|--|

|    |                  |                                     |                                  |   |  |
|----|------------------|-------------------------------------|----------------------------------|---|--|
| 29 | <b>R104-8300</b> | 104-8300,<br>104-8300 ,<br>119-4041 | Locknut - 5/16-18 Flanged Y/Zinc | 5 |  |
|----|------------------|-------------------------------------|----------------------------------|---|--|

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Greensmaster 300 Parts

*Dethatcher Unit - Model 04479*

*Rear Roller Brush - Model 04650*



| Item No | R&R Part No. | OEM Part No.        | Description               | Qty Req | Order Quantity |
|---------|--------------|---------------------|---------------------------|---------|----------------|
| 30      | R3234-29     | 3234-17,<br>3234-29 | Bolt - 5/16-18x1 Serr Hex | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.